

#### State of Utah

#### Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

## Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Kit Pappas Manager of Environmental/Engineering
OGM	Karl Houskeeper Environmental Scientist III

# **Inspection Report**

Permit Number:	C0070020		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, April 28, 2008		
Start Date/Time:	4/28/2008 9:30:00 AM		
End Date/Time:	4/28/2008 12:30:00 PM		
Last Inspection:	Monday, March 31, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 63 Deg. F. InspectionID Report Number: 1627

Permitee: HIDDEN SPLENDOR RESOURCES INC Operator: HIDDEN SPLENDOR RESOURCES INC

Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

Mineral Ownership

**Types of Operations** 

✓ Underground ☐ Surface ☐ Loadout Processing Reprocessing

<b>✓</b> Federal	<b>Total Permitted</b>	1,577.00
☐ State	<b>Total Disturbed</b>	9.50
☐ County	Phase I	
<b>✓</b> Fee	Phase II	
Other	Phase III	

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

**Date** 

Monday, April 28, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Monday, April 28, 2008

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	∠ Lvaluateu	Not Applicable	<b>✓</b>	
2.	Signs and Markers	<u> </u>		<b>✓</b>	
3.	Topsoil	П			
4.a	Hydrologic Balance: Diversions	<b>✓</b>	П		
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>	П		
4.c	Hydrologic Balance: Other Sediment Control Measures	П			П
4.d	Hydrologic Balance: Water Monitoring	<u> </u>		<b>V</b>	
4.e	Hydrologic Balance: Effluent Limitations				
 5.	Explosives	<u> </u>			
6.	Disposal of Excess Spoil, Fills, Benches	<u> </u>	<u> </u>		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<u> </u>	<u> </u>		
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
	Revegetation				П
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Monday, April 28, 2008

Page 3 of 3

# 1. Permits, Change, Transfer, Renewal, Sale

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

#### 2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, address, phone number, permit number, and MSHA number.

# 4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2007water monitoring information is in the EDI website and has been uploaded. Water monitoring is current.